

Oxygen settings	Tank (PMG only)	O ₂ %	ppO ₂ /MOD
------------------------	-----------------	------------------	-----------------------

Dive settings	MB level	Gauge mode	Safety stop timer	ppO ₂ max	Nitrox reset time	Water type	Desaturation reset	All-silent mode	PMG
----------------------	----------	------------	-------------------	----------------------	-------------------	------------	--------------------	-----------------	-----

Digital compass	Surface use	Auto-off time	Declination
------------------------	-------------	---------------	-------------

Altimeter	Use	Adjustment
------------------	-----	------------

Warning settings	Max depth	CNS O ₂ = 75%	No-stop= 2min	Entering deco	Dive time	Tank pressure	RBT= 3 min	Pressure signal	Entering level stops	MB stop ignored	MB level reduced	LO No-stop= 2 min	MB entering deco
-------------------------	-----------	--------------------------	---------------	---------------	-----------	---------------	------------	-----------------	----------------------	-----------------	------------------	-------------------	------------------

Clock	Alarm	Adjust	Time zone
--------------	-------	--------	-----------

Other settings	Device info	Gas integration	Backlight duration	Display contrast	IrDA speed	Water contacts	Revert to factory settings
-----------------------	-------------	-----------------	--------------------	------------------	------------	----------------	----------------------------

Personalization	Screen configuration	Language	Start-up picture	Units	Workload	Owner info	Emergency info
------------------------	----------------------	----------	------------------	-------	----------	------------	----------------

Pictures	View pictures
-----------------	---------------

Dive planner	Surface interval	No-stop plan	Deco plan
---------------------	------------------	--------------	-----------

Logbook	View logbook
----------------	--------------

